

Pressure Conversion Chart

	PSI	KPA	Inches H ₂ O (20° C)	Cm H ₂ O (20° C)	Inches Hg (0° C)	mm Hg (0° C)	Bars	mBars	Kg/cm ²
PSI	1	6.8948	27.7296	70.4332	2.0360	51.7149	.0689	68.9476	.0703
KPA	0.1450	1	4.0218	10.2155	0.2953	7.5006	.0100	10.0000	0.0102
Inches H ₂ O (20° C)	0.0361	0.2486	1	2.5400	0.0734	1.8650	0.0025	2.4864	0.0025
Cm H ₂ O (20° C)	0.0142	0.0979	0.3937	1	0.0289	0.7342	0.0010	0.9790	0.0001
Inches Hg (0° C)	0.4912	3.3864	13.6195	34.5936	1	25.4000	0.0339	33.8639	0.0345
mm Hg (0° C)	0.0193	0.1333	0.5362	1.3620	0.0394	1	.0013	1.3332	.0014
Bars	14.5038	100.000	402.184	1021.55	29.5300	750.062	1	1000	1.0197
mBars	0.0145	.1000	0.4022	1.0216	0.0295	0.7501	.001	1	.0010
Kg/cm ²	14.2233	98.0665	394.408	1001.80	28.9590	735.559	.9807	980.665	1



Unit 3a Mansfield Park
 Four Marks, Alton
 Hants, GU34 5PZ
 Tel: ++ 44 (0) 1420 568150
 Fax: ++ 44 (0) 1420 568151
www.labcell.com

